

Changing from PMT Detectors to InGaAs

Open-architecture and good design result in fail-safe and tool-free modularity when exchanging detectors (shown), gratings, cuvette holders, and all accessories.



First, the thumbscrews holding the panel in place are removed.



Then, the PMT cables are released by pressing the small lever on the side of each.



Remove the detector panel as shown. Replace with the new panel by reversing these steps.